


shifting means for displacing the rotary device in a direction parallel to the longitudinal axis; and different guides for guiding the base plate and the second mold mounting plate.

IN THE DRAWING:

Amend FIG. 1 as per copy enclosed and indicated in red.



1 / 5

一
五

